


































FgArea: [' C4' ]  
NJ15 L1  
2026-04-01 (Day 177)







Plot [['EcFgro', 'EcFzExp', 'EcPltng', 'ECdef', 'EcParam', 'water\_ec']]








Plot [ ' ECopt' ]




L1AC4\_C4: M\_W79





Plot Sensor and FgRec Data




Plot preM vs WCperM




Plot [['ETcA\_VN', 'ETcA\_ws'], ['ETcB\_VN', 'ETcB\_ws']]




Plot [['ETcAraw:o', 'ETcA']]




Plot [['ETcBraw:o', 'ETcB']]







Plot [['taoc', 'taoc\_raw:ro', 'taoc\_avg:r-']]







Plot [['setVI\_ETcI', 'setVI\_fgRec', 'setVI\_VN', 'sISetVI']]







Plot ET/VN




Plot Fv and fertilizer usage




Fertilizer Range Source: kerleyL, kerleyH, UnivFL, TNAI, Haifa










Trend plot for L1AC4\_C4





# FgDaily














A阀开关时间(秒)	B阀开关
'关' : 17, '占空比' : 95.0}, {'开' : 35, '关' : 47, '占空比' : 95.0}]	[{'开' : 18, '关' : 30, '占空比' : 95.0},
'关' : 17, '占空比' : 95.0}, {'开' : 35, '关' : 47, '占空比' : 95.0}]	[{'开' : 18, '关' : 30, '占空比' : 95.0},


















## A阀开关时间(秒)


['开': 5, '关': 17, '占空比': 95.0], ['开': 35, '关': 47, '占空比': 95.0]
['开': 5, '关': 17, '占空比': 95.0], ['开': 35, '关': 47, '占空比': 95.0]

[['开': 18, '关': 30, '占空比':
[['开': 18, '关': 30, '占空比':

上次灌溉流速比过去5天平均小 (0.21 vs 0.6), 可能管道压力异常或有管道堵塞  
 施肥机灌溉量与预期值不符 (15.0 : 36.0), 可能水表需要校准  
 默认实际灌溉36.0 ml.  
 上次灌溉施肥机流速0.207736092068636与平均值0.6偏差较大, 请检查。










L1AC4

A阀开关时间(秒) ['开': 5, '关': 17, '占空比': 95.0], ['开': 35, '关': 47, '占空比': 95.0]	B阀 ['开': 18, '关': 30, '占空比': 95.0]
--	---------------------------------------








A阀开关时间(秒)		
['开': 5, '关': 17, '占空比': 95.0], ['开': 35, '关': 47, '占空比': 95.0]		['开': 18, '关': 30, '占空比': 95.0]
['开': 5, '关': 17, '占空比': 95.0], ['开': 35, '关': 47, '占空比': 95.0]		['开': 18, '关': 30, '占空比': 95.0]
['开': 5, '关': 17, '占空比': 95.0]		
['开': 5, '关': 17, '占空比': 95.0], ['开': 35, '关': 47, '占空比': 95.0]		['开': 18, '关': 30, '占空比': 95.0]
['开': 5, '关': 17, '占空比': 95.0], ['开': 35, '关': 47, '占空比': 95.0]		['开': 18, '关': 30, '占空比': 95.0]













上次灌溉流速比过去5天平均小 (0.21 vs 0.59), 可能管道压力异常或有管道堵塞


施肥机灌溉量与预期值不符 (15.0 : 35.0), 可能水表需要校准

默认实际灌溉35.0 ml.

上次灌溉施肥机流速0.21070375052675938与平均值0.59偏差较大, 请检查。







A阀开关时间(秒)		
['开': 5, '关': 17, '占空比': 95.0], ['开': 35, '关': 47, '占空比': 95.0]		['开': 18, '关': 30, '占空比': 95.0]
['开': 5, '关': 17, '占空比': 95.0], ['开': 35, '关': 47, '占空比': 95.0]		['开': 18, '关': 30, '占空比': 95.0]
	['开': 5, '关': 17, '占空比': 95.0]	
['开': 5, '关': 17, '占空比': 95.0], ['开': 35, '关': 47, '占空比': 95.0]		['开': 18, '关': 30, '占空比': 95.0]
	['开': 5, '关': 17, '占空比': 95.0]	
['开': 5, '关': 17, '占空比': 95.0], ['开': 35, '关': 47, '占空比': 95.0]		['开': 18, '关': 30, '占空比': 95.0]

上次灌溉流速比过去5天平均小 (0.2 vs 0.59), 可能管道压力异常或有管道堵塞  
 施肥机灌溉量与预期值不符 (15.0 : 36.0), 可能水表需要校准

默认实际灌溉36.0 ml.

上次灌溉施肥机流速0.20485086856768273与平均值0.59偏差较大, 请检查。

