


































FgArea: [' C5' ]  
NJ15 L1  
2026-03-20 (Day 165)










Plot [['EcFgro', 'EcFzExp', 'EcPltng', 'ECdef', 'EcParam', 'water\_ec']]





Plot [' ECopt ']




Plot Sensor and FgRec Data




Plot [['ETcA\_VN', 'ETcA\_ws'], ['ETcB\_VN', 'ETcB\_ws']]




Plot [['ETcAraw:o', 'ETcA']]




Plot [['ETcBraw:o', 'ETcB']]







Plot [['taoc', 'taoc\_raw:ro', 'taoc\_avg:r-']]







Plot [['setVI\_ETcI', 'setVI\_fgRec', 'setVI\_VN', 'sISetVI']]







Plot ET/VN




Plot Fv and fertilizer usage




Fertilizer Range Source: kerleyL, kerleyH, UnivFL, TNAI, Haifa










Trend plot for L1A05\_C5





# FgDaily













A阀开关时间(秒)	B阀开关
'关' : 14, '占空比' : 50.0}, {'开' : 35, '关' : 44, '占空比' : 50.0}]	[{'开' : 15, '关' : 24, '占空比' : 50.0},
'关' : 14, '占空比' : 50.0}, {'开' : 35, '关' : 44, '占空比' : 50.0}]	[{'开' : 15, '关' : 24, '占空比' : 50.0},

上次灌溉流速比过去5天平均小 (0.42 vs 0.61), 可能管道压力异常或有管道堵塞  
 施肥机灌溉量与预期值不符 (29.0 : 35.0), 可能水表需要校准  
 默认实际灌溉35.0 ml.















A阀开关时间(秒)	B阀开
: 5, '关' : 14, '占空比' : 50.0], ['开' : 35, '关' : 44, '占空比' : 50.0]	[['开' : 15, '关' : 24, '占空比' : 50.0
: 5, '关' : 14, '占空比' : 50.0], ['开' : 35, '关' : 44, '占空比' : 50.0]	[['开' : 15, '关' : 24, '占空比' : 50.0
: 5, '关' : 14, '占空比' : 50.0], ['开' : 35, '关' : 44, '占空比' : 50.0]	[['开' : 15, '关' : 24, '占空比' : 50.0
: 5, '关' : 14, '占空比' : 50.0], ['开' : 35, '关' : 44, '占空比' : 50.0]	[['开' : 15, '关' : 24, '占空比' : 50.0
: 5, '关' : 14, '占空比' : 50.0], ['开' : 35, '关' : 44, '占空比' : 50.0]	[['开' : 15, '关' : 24, '占空比' : 50.0


上次灌溉流速比过去5天平均小 (0.2 vs 0.61), 可能管道压力异常或有管道堵塞  
 施肥机灌溉量与预期值不符 (15.0 : 36.0), 可能水表需要校准

默认实际灌溉36.0 ml.

上次灌溉施肥机流速0.20485086856768273与平均值0.61偏差较大, 请检查。










L1A05

A阀开关时间(秒) '关': 14, '占空比': 50.0], ['开': 35, '关': 44, '占空比': 50.0]	B阀开关时间(秒) ['开': 15, '关': 24, '占空比': 50.0], ['开': 15, '关': 24, '占空比': 50.0]
---	---










L1A05

A阀开关时间(秒) '关': 14, '占空比': 50.0], ['开': 35, '关': 44, '占空比': 50.0]	B阀开关时间(秒) ['开': 15, '关': 24, '占空比': 50.0], ['开': 15, '关': 24, '占空比': 50.0]
---	---







A阀开关时间(秒) '关': 14, '占空比': 50.0], {'开': 35, '关': 44, '占空比': 50.0}]	B阀开关时间(秒) [{'开': 15, '关': 24, '占空比': 50.0}, {'开': 15, '关': 24, '占空比': 50.0}]
--	---

上次灌溉流速比过去5天平均小 (0.2 vs 0.7), 可能管道压力异常或有管道堵塞  
 施肥机灌溉量与预期值不符 (15.0 : 36.0), 可能水表需要校准  
 默认实际灌溉36.0 ml.

